

Appendix 7 - Email from the Environment agency with photographs attached dated 9 July 2019

RE: Test




Jesson, Toby
To Chantrell Neal

👍 Reply Reply All Forward ...

Tue 09/07/2019 15:55

You forwarded this message on 10/07/2019 10:29.



Hi Neil,

I have had a look at the site this morning and there is still a large amount of soil that has been used to raise the ground height, our flood mapping is attached. The site comprises elements of FZ3a / 3b and FZ2. The fact that some of the ground raising seems to have taken place in FZ3b (green area on the map) should be concerning as this is the functional floodplain so has a high probability of flooding, flood water which would now be pushed elsewhere do to the ground raising.

Best regards

Toby

Toby Jesson

FCRM Officer, Asset Performance South

Environment Agency | Rothley Office, 56 Town Green Street, Rothley, Leicestershire, LE7 7NW

External:

Working days: Monday to Friday



